Men's Wearhouse

650 6th Avenue New York, NY 10011

Inspection date: September 9, 2014

Introduction

Title III of the Americans with Disabilities Act of 1990 ("ADA") prohibits disability discrimination by places of public accommodations. The ADA requires places of public accommodation that are "newly constructed" or "altered" on or after January 26, 1992 to comply with the ADA Standards for Accessible Design (the "Standards") identified below. The ADA also requires places of public accommodation existing before January 26, 1992 to continually engage in the removal of barriers that are "readily achievable".

In 1991, the United States Department of Justice adopted as regulations for Title III of the ADA enforceable accessibility standards known as the Standards for Accessible Design ("1991 Standards"). On September 15, 2010, the United States Department of Justice issued revised regulations for Title III of the ADA, which adopted revised enforceable accessibility standards known as the 2010 ADA Standards for Accessible Design ("2010 Standards"). New construction and alterations, including alterations related to barrier removal completed before March 15, 2012 must comply with either the 1991 Standards or the 2010 Standards. After March 15, 2012, however, compliance with the 2010 Standards became mandatory for new construction and alterations, including alterations related to barrier removal.

New York City Local Law 58 of 1987 ("LL 58/87") established minimum accessibility standards for places of public accommodations in New York City. Pursuant to LL 58/87, whenever accessibility standards pursuant to New York City laws are more stringent than the Standards referenced above, the New York City accessibility standards apply.

Objectives

This report outlines the findings of a September 9, 2014 site inspection of Men's Wearhouse located at 650 6th Avenue, New York, NY 10011. This report includes an overview of the facility where Men's Wearhouse is located with a primary focus on elements that do not conform to Title III of the ADA (the 1991 Standards and 2010 Standards) as well as relevant local regulations. This review is not intended to be a comprehensive survey of all accessibility requirements. The primary focus of this review and recommendations covers access for people with mobility issues.

The 1991 Standards and the 2010 Standards were used as the accessibility reference standards. Specific citations from the 2010 Standards are noted in the "Citation" column below and designated "2010". Citations from the 1991 Standards are also provided and designated "1991". Further citations from the 2010 Standards and 1991 Standards are often provided in the "Note" column as additional information. In circumstances where the 1991 Standards are different from the 2010 Standards, the difference is mentioned in the "Note" column of the report.

The 2010 Standards and the 1991 Standards in their entirety are available at the US Access Board's website at www.access-board.gov.

Specific citations to the New York City Building Code and Administrative Code are also noted in the "Citation" column of the report. Generally, permits issued after July 01, 2008 are subject to the "2008" Building Code. Permits issued prior to July 01, 2008 are subject to the "1968" Building Code.

Recommendations based on the findings of the inspection have been provided in the "Recommendation" column. In addition to physical access issues for persons with mobility disabilities due to architectural and design barriers there are also policy and operational issues that affect accessibility for persons with mobility. As such, there is a need for the facility to provide ongoing training for its entire staff including strategies and procedures for including people with disabilities in all of its services. It is also important for the facility to provide an opportunity for people with disabilities to recommend further enhancements that might be beneficial for all people with disabilities.

Description

Men's Warehouse is a retail facility located on the east side of 6th Avenue between 19th Street and 20th Street in Manhattan.

There is one (1) general public entrance to the Men's Warehouse store on 6th Avenue. This entrance is not accessible due to steps at the exterior side of the entrance and a lack of pull side maneuvering clearance at the entrance door.

Men's Warehouse covers one (1) level containing men's clothing, primarily men's suits. Two (2) dressing areas are located along the south side of the facility, containing 9 total dressing rooms. 6 dressing rooms are provided in dressing area 1 (noted as "southwest dressing room area") and 3 dressing rooms are in dressing area 2 (noted as "southeast dressing room area"). Both the southwest and the southeast dressing areas contain a large dressing room that appears to be provided for people with mobility issues. However both large dressing rooms are not labeled as accessible nor are the fully accessible.

There is an emergency exit on the north side of the faculty leading through a separate tenant lobby to 20th Street. The emergency exit is not accessible due to the lack of an accessible route leading to the exit door.

Report

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
Entrance	es					•
001	An accessible route is not provided from the sidewalk to the Men's Wearhouse entrance. See items 002 to 004.	2010 -206.2.1 1991 -4.1.2(1) -4.3 2008 -1104.1	At least one accessible route shall be provided within the site from public streets and sidewalks and public transportation stops to the accessible building or facility entrance they serve.		See items 002 to 004.	AA
002	An accessible entrance is not provided to the Men's Wearhouse store. See items 003 to 004.	2010 -206.4.1 -404.2.9 1991 -4.1.3(8) 2008 -1105.1	At least 60 percent of all public entrances shall be accessible.	1991 Standards section 4.1.3(8) requires 50 percent of all public entrances be accessible. 2008 NYC building code section 1105.1 requires ALL entrances be accessible. See items 003 to 004.	See items 003 to 004.	AA
003	There is a step between the public sidewalk and the Men's Wearhouse entrance. There is approximately a 9 inch change in elevation between the sidewalk and the entrance door.	2010 -303.4	Changes in level greater than 1/2 inch high shall be ramped.		Provide a ramp.	AB

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAG
004	Only 35 inches of front approach pull side clearance is provided perpendicular to the Men's Wearhouse entrance door due to the steps.	2010 -404.2.4 1991 -4.13.6	Swinging doors and gates shall have level maneuvering clearances. 60 inches of front approach pull side clearance is required perpendicular to doorway.		When providing a ramp for item 003, ensure the required level maneuvering clearances are also provided at the entrance door.	AC
		-2008 -404.2.3				
xits						
005	The exit door on the north side of the facility leading through a separate tenant lobby to 20th Street is not accessible. No accessible exits from the Men's Wearhouse store are provided since the entrance door is also not accessible. See items 006 and 002.	2010 -207.1 1991 -4.1.3(9) 2008 -1007.1	Accessible spaces shall be provided with not less than one accessible means of egress. Where more than one means of egress is required from any accessible space, each accessible portion of the space shall be served by not less than two accessible means of egress.		Provide at least two accessible means of egress from accessible spaces as required. Identify exit doors with tactile signs complying with 703.1, 703.2, and 703.5. See items 006 and 002.	-
006	Merchandise obstructs the accessible route to the exit. Only 31 inches is provided between merchandise and the wing wall.	2010 -403.5.1 1991 -4.1.3(3) -4.3.3 2008	The clear width of walking surfaces along accessible routes shall be 36 inches minimum.		Relocate merchandise so that 36 inches is provided along the accessible route to the exit between the merchandise and the wing wall.	AD
		-403.5				
Service C		1	1	T		
007	The front service counter is 36-1/2 inches above the finish floor.	2010 -227.1 -904.4 1991	A portion of the service counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided.		Provided a section of counter that is 36 inches long minimum and 36 inches high maximum above the finish floor.	AE
007		-7.2(1) 2008 -904.3.1	De provided.			AL

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
	The rear service counter is not	2010	A clear floor or ground space shall be		Permanently remove some chairs so	
	provided with a clear floor space due	-227.1	positioned for a parallel approach		that a clear floor space is always	
	to the chairs.	-904.4	adjacent to accessible service		provided at the rear service counter.	
			counters.			
008		1991				AF
		-7.2(1)				
		2008				
		-904.2				
Accessib	le Routes					
	Throughout the Men's Wearhouse	2010	At least one accessible route shall	See items 010 to 033.	See items 010 to 033.	
	store: Accessible routes are not	-206.2.2	connect accessible buildings,			
	connecting accessible spaces.		accessible facilities, accessible			
	Note: Management noted that	1991	elements, and accessible spaces that			
	customers do not access	-4.1.3(1)	are on the same site.			
	merchandise in the jacket, pant, and	-4.3.2(2)				
009	coat areas. However customers were					_
003	observed shopping in these sections.	2008				
	Furthermore, employee work areas	-1104.2				
	must be constructed so that					
	individuals with disabilities can					
	approach, enter, and exit employee					
	work areas.					
	See items 010 to 033.					
	North side of the store at the first	2010	The clear width of walking surfaces		Relocate merchandise so that 36	
	jacket area: Merchandise obstructs	-403.5.1	along accessible routes shall be 36		inches is provided at aisles	
	accessible routes. Only 12 inches is		inches minimum.		throughout the store.	
	provided between merchandise at	1991				
010	the center aisle.	-4.1.3(3)				AG
		-4.3.3				
		2008				
	Name of a state of the state of the first	-403.5	NA/Is and Also a constitute of the constitute of		Delegate granden dies es that 42	
	North side of the store at the first	2010 -403.5.2	Where the accessible route makes a		Relocate merchandise so that 42	
	jacket area: Only 23 inches is	-403.5.2	180 degree turn around an element		inches minimum approaching the	
	provided approaching the turn for	1001	which is less than 48 inches wide,		turn is provided for going around the	
011	going around the end caps.	1991	clear width shall be 42 inches		end caps.	AG
		-4.3.3	minimum approaching the turn, 48			
		2000	inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
	1	-403.5.1				

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMA
	North side of the store at the first	2010	Where the accessible route makes a		Relocate merchandise so that 48	
	jacket area: Only 32 inches is	-403.5.2	180 degree turn around an element		inches minimum at the turn is	
	provided at the turn for going around		which is less than 48 inches wide,		provided for going around the end	
012	the end caps.	1991	clear width shall be 42 inches		caps.	А
012		-4.3.3	minimum approaching the turn, 48			
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	North side of the store at the first	2010	Where the accessible route makes a		Relocate merchandise so that 42	
	jacket area: Only 18 inches is	-403.5.2	180 degree turn around an element		inches minimum leaving the turn is	
	provided leaving the turn for going		which is less than 48 inches wide,		provided for going around the end	
013	around the end caps.	1991	clear width shall be 42 inches		caps.	<i>,</i>
013		-4.3.3	minimum approaching the turn, 48			,
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	North side of the store at the first	2010	The clear width of walking surfaces		Relocate merchandise so that 36	
	jacket area: Merchandise and the	-403.5.1	along accessible routes shall be 36		inches is provided for going around	
	column obstruct accessible routes.		inches minimum.		the column.	
	Only 21 inches is provided between	1991				
014	merchandise and the column.	-4.1.3(3)				A
		-4.3.3				
		2008				
		-403.5				
	North side of the store at the second	2010	Where the accessible route makes a		Relocate merchandise so that 42	
	jacket area: Only 34 inches is	-403.5.2	180 degree turn around an element		inches minimum approaching the	
	provided approaching the turn for		which is less than 48 inches wide,		turn is provided for going around the	
015	going around the end caps.	1991	clear width shall be 42 inches		end caps.	
		-4.3.3	minimum approaching the turn, 48			
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	North side of the store at the second	2010	Where the accessible route makes a		Relocate merchandise so that 48	
	jacket area: Only 32 inches is	-403.5.2	180 degree turn around an element		inches minimum at the turn is	
	provided at the turn for going around		which is less than 48 inches wide,		provided for going around the end	
016	the end caps.	1991	clear width shall be 42 inches		caps.	
		-4.3.3	minimum approaching the turn, 48			·
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
	North side of the store at the second jacket area: Only 32 inches is	2010 -403.5.2	Where the accessible route makes a 180 degree turn around an element		Relocate merchandise so that 42 inches minimum leaving the turn is	
	provided leaving the turn for going	403.3.2	which is less than 48 inches wide,		provided for going around the end	
	around the end caps.	1991	clear width shall be 42 inches		caps.	
017	around the end caps.	-4.3.3	minimum approaching the turn, 48		cups.	Al
		4.5.5	inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1	linenes minimum reaving the tarm			
	North side of the store at the second	2010	The clear width of walking surfaces		Relocate merchandise so that 36	
	jacket area: Merchandise and the	-403.5.1	along accessible routes shall be 36		inches is provided for going around	
	column obstruct accessible routes.		inches minimum.		the column.	
	Only 13 inches is provided between	1991				
018	merchandise and the column.	-4.1.3(3)				AJ
		-4.3.3				
		2008				
		-403.5				
	North side of the store at the third	2010	Where the accessible route makes a		Relocate merchandise so that 48	
	jacket area: Only 32 inches is	-403.5.2	180 degree turn around an element		inches minimum at the turn is	
	provided at the turn for going around		which is less than 48 inches wide,		provided for going around the end	
019	the end caps.	1991	clear width shall be 42 inches		caps.	AK
013		-4.3.3	minimum approaching the turn, 48			AK
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	North side of the store at the third	2010	Where the accessible route makes a		Relocate merchandise so that 42	
	jacket area: Only 21 inches is	-403.5.2	180 degree turn around an element		inches minimum leaving the turn is	
	provided leaving the turn for going		which is less than 48 inches wide,		provided for going around the end	
020	around the end caps.	1991	clear width shall be 42 inches		caps.	AK
		-4.3.3	minimum approaching the turn, 48			
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
	N. H. S. C. L.	-403.5.1	-		2 1 1 1 1 1 2 2	
	North side of the store at the third	2010	The clear width of walking surfaces		Relocate merchandise so that 36	
	jacket area: Merchandise and the column obstruct accessible routes.	-403.5.1	along accessible routes shall be 36 inches minimum.		inches is provided for going around the column.	
	Only 19 inches is provided between	1991	inches minimum.		the column.	
021	merchandise and the column.	-4.1.3(3)				AL
UZI	interchandise and the column.	-4.1.3(3) -4.3.3				AL
		-4.3.3				
		2008				
		-403.5				
		-403.3				

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
	North side of the store at the pants	2010	Where the accessible route makes a		Relocate merchandise so that 48	
	area: Only 24 inches is provided at	-403.5.2	180 degree turn around an element		inches minimum at the turn is	
	the turn for going around the end		which is less than 48 inches wide,		provided for going around the end	
022	caps.	1991	clear width shall be 42 inches		caps.	AM
022		-4.3.3	minimum approaching the turn, 48			Alvi
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	North side of the store at the pants	2010	Where the accessible route makes a		Relocate merchandise so that 42	
	area: Only 35 inches is provided	-403.5.2	180 degree turn around an element		inches minimum leaving the turn is	
	leaving the turn for going around the		which is less than 48 inches wide,		provided for going around the end	
023	end caps.	1991	clear width shall be 42 inches		caps.	AM
023		-4.3.3	minimum approaching the turn, 48			Alvi
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	North side of the store at the coat	2010	The clear width of walking surfaces		Relocate the mannequin so that 36	
	area: Displays obstruct accessible	-403.5.1	along accessible routes shall be 36		inches is provided to the coat area.	
	routes. Only 20 inches is provided		inches minimum.			
	between the mannequin and the	1991				
024	wall.	-4.1.3(3)				AN
		-4.3.3				
		2008				
		-403.5				
	North side of the store at the coat	2010	The clear width of walking surfaces		Relocate the table so that 36 inches is	
	area: Displays obstruct accessible	-403.5.1	along accessible routes shall be 36		provided to the coat area.	
	routes. Only 20 inches is provided		inches minimum.			
	between the table and the coats.	1991				
025		-4.1.3(3)				AO
		-4.3.3				
		2008				
		-403.5				
	South side of the store at the clothes	2010	The clear width of walking surfaces		Relocate merchandise so that 36	
	area: Merchandise obstructs	-403.5.1	along accessible routes shall be 36		inches is provided at aisles	
	accessible routes. Only 26 inches is		inches minimum.		throughout the store.	
	provided between merchandise at	1991				
026	the center aisle.	-4.1.3(3)				AP
		2008				
		-403.5				
		-4.3.3				

ITEM	ISSUE	ĺ	CITATION	NOTE	RECOMMENDATION	IMAGE
	South side of the store at the clothes	2010	Where the accessible route makes a		Relocate merchandise so that 42	
	area: Only 18 inches is provided	-403.5.2	180 degree turn around an element		inches minimum approaching the	
	approaching the turn for going		which is less than 48 inches wide,		turn is provided for going around the	
027	around the end caps.	1991	clear width shall be 42 inches		end caps.	40
027		-4.3.3	minimum approaching the turn, 48			AQ
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	South side of the store at the clothes	2010	Where the accessible route makes a		Relocate merchandise so that 48	
	area: Only 39 inches is provided at	-403.5.2	180 degree turn around an element		inches minimum at the turn is	
	the turn for going around the end		which is less than 48 inches wide,		provided for going around the end	
020	caps.	1991	clear width shall be 42 inches		caps.	4.0
028		-4.3.3	minimum approaching the turn, 48		·	AR
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	South side of the store at the clothes	2010	Where the accessible route makes a		Relocate merchandise so that 42	
	area: Only 26 inches is provided	-403.5.2	180 degree turn around an element		inches minimum leaving the turn is	
	leaving the turn for going around the		which is less than 48 inches wide,		provided for going around the end	
020	end caps.	1991	clear width shall be 42 inches		caps.	
029		-4.3.3	minimum approaching the turn, 48			-
			inches minimum at the turn and 42			
		2008	inches minimum leaving the turn.			
		-403.5.1				
	South side of the store at the clothes	2010	The clear width of walking surfaces		Relocate merchandise and displays so	
	area: Merchandise and displays	-403.5.1	along accessible routes shall be 36		that 36 inches is provided at aisles	
	obstruct accessible routes. Only 26		inches minimum.		throughout the store.	
	inches is provided between the	1991				
030	displays at the clothes area.	-4.1.3(3)				AS
		-4.3.3				
		2008				
		-403.5				
	South side of the store at the clothes	2010	The clear width of walking surfaces		Relocate merchandise and displays so	
	area: Merchandise and displays	-403.5.1	along accessible routes shall be 36		that 36 inches is provided at aisles	
	obstruct accessible routes. Only 20		inches minimum.		throughout the store.	
	inches is provided between the	1991				
031	displays at the clothes area.	-4.1.3(3)				-
		-4.3.3				
		2008				
		-403.5				

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
032	South side of the store at the clothes area: Merchandise and the column obstruct accessible routes. Only 17 inches is provided between merchandise and the column.	2010 -403.5.1 1991 -4.1.3(3) -4.3.3 2008 -403.5	The clear width of walking surfaces along accessible routes shall be 36 inches minimum.		Relocate merchandise so that 36 inches is provided for going around the column.	AT
033	South side of the store at the clothes area: Merchandise and displays obstruct accessible routes. Only 24 inches is provided between the displays at the clothes area.	2010 -403.5.1 1991 -4.1.3(3) -4.3.3 2008 -403.5	The clear width of walking surfaces along accessible routes shall be 36 inches minimum.		Relocate merchandise and displays so that 36 inches is provided at aisles throughout the store.	AU
Dressing		1				
034	Accessible dressing rooms are not provided. See items 035 and 044.	2010 -222.1 1991 -4.1.3(21) 2008 -1109.12.1	Where dressing rooms, fitting rooms, or locker rooms are provided, at least 5 percent, but no fewer than one, of each type of use in each cluster provided shall be accessible.	See items 035 and 044.	Provide 5 percent accessible dressing rooms complying with 2010 Standards section 803. 2008 NYC building code section 1110.1(8) requires accessible dressing rooms be identified by the International Symbol of Accessibility. See items 035 and 044.	-
035	West dressing room area: Only 35-1/2 inches is provided at the opening to the dressing room area.	2010 -403.5.1 1991 -4.1.3(3) -4.3.3 2008 -403.5	The clear width of walking surfaces along accessible routes shall be 36 inches minimum.		Widen the opening to the dressing room area so that 36 inches is provided.	AV
036	West dressing room area: Only 30-1/2 inches of latch approach pull side clearance is provided perpendicular to the large dressing room entry door due to furniture.	2010 -404.2.4	Swinging doors and gates shall have maneuvering clearances. 48 inches of latch approach pull side clearance is required perpendicular to doorway.		Relocate the furniture so that it is not in the maneuvering clearance of the door to the large dressing room.	AW

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
037	West dressing room area: The large dressing room is only 59 inches x 60-1/2 inches and lacks a turning space.	2010 -803.2 1991 -4.35.2 2008	A 60 inches diameter minimum turning space shall be provided within the room.		Reconfigure dressing rooms as necessary so that the large dressing room is provided with a 60 inch turning diameter.	AX
038	West dressing room area: The bench within the large dressing room is not provided with a clear floor space for transfer.	-803.2 2010 -803.4 1991 -4.35.4 2008	Clear floor or ground space shall be provided at benches and shall be positioned at the end of the bench seat and parallel to the short axis of the bench.		Reconfigure dressing rooms as necessary so that the large dressing room is provided with an accessible bench complying with 2010 Standards section 903.	AY
039	East dressing room area: Only 35 inches is provided at the opening to the dressing room area.	-803.4 2010 -403.5.1 1991 -4.1.3(3) -4.3.3 2008	The clear width of walking surfaces along accessible routes shall be 36 inches minimum.		Widen the opening to the dressing room area so that 36 inches is provided.	AZ
040	East dressing room area: Only 46-1/2 inches of latch approach pull side clearance is provided perpendicular to the large dressing room entry door due to the wall.	-404.2.4	Swinging doors and gates shall have maneuvering clearances. 48 inches of latch approach pull side clearance is required perpendicular to doorway.		Relocate the wall so that it is not in the maneuvering clearance of the door to the large dressing room.	ВА
041	West dressing room area: The bench within the large dressing room is not provided with a clear floor space for transfer.	2010 -803.4 1991 -4.35.4 2008 -803.4	Clear floor or ground space shall be provided at benches and shall be positioned at the end of the bench seat and parallel to the short axis of the bench.		Reconfigure dressing rooms as necessary so that the large dressing room is provided with an accessible bench complying with 2010 Standards section 903.	ВВ

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE
	East dressing room area: The mirror	2010	A 60 inches diameter minimum		Permanently remove the chairs so	
	area is only 50 inches wide and lacks	-803.2	turning space shall be provided		that the mirror area is always	
	a turning space due to the chairs.		within the room.		provided with a 60 inch turning	
042		1991			diameter.	ВС
042		-4.35.2				ВС
		2008 -803.2				
Reach Ra	nnges	-803.2				
Neacii Na	T T	2010	Whom a closu floor or around space	1001 Standards section 4.3 C requires	Dunido signogo indication accistomas	
	Throughout the Men's Wearhouse:	2010	Where a clear floor or ground space	1991 Standards section 4.2.6 requires		
	Merchandise is outside of accessible	-308.3.1	allows a parallel approach to an	the side reach be 54 inches	is available for merchandise outside	
	reach ranges.		element and the side reach is	maximum and 9 inches minimum	of accessible reach ranges.	
	Some dress shirts are 77 inches	1991	unobstructed, the side reach shall be	above the finish floor.		
043	above the finish floor.	-4.2.6	48 inches maximum and 15 inches	2008 NYC building code and its		BD
043	Some belts and socks are 89 inches		minimum above the finish floor.	reference standard ANSI A117.1-2003		ΒD
	above the finish floor.	2008		section 308.3.1 requires the side		
	Some clothes are 90 inches above the	-308.3.1		reach be 48 inches maximum and 15		
	finish floor.			inches minimum above the finish		
				floor.		

ITEM	ISSUE		CITATION	NOTE	RECOMMENDATION	IMAGE		
Protrudir	truding Objects							
	Throughout the Men's Wearhouse	2010	Objects with leading edges between		Reduce the length of the clothes			
	store: The clothes display rods	-204.1	27 inches and 80 inches above the		display rods so that they project no			
	project horizontally 5-1/2 inches into	-307.1	finish floor shall not protrude more		more than 4 inches into the			
	the circulation paths.		than 4 inches horizontally into the		circulation paths.			
		1991	circulation path.					
044		-4.1.3(2)				BE		
		-4.4.1						
		2008						
		-307.1						
			End Repor	t				
This repor	This report was prepared by Jimmy Zuehl, Architectural Accessibility Consultant.							
00								
0 4 4	Septe	mber 22 2014	<u> </u>					
Jimmy Zue	ehl Date							

Men's Wearhouse 650 6th Avenue New York, NY 10011 Inspection date: September 9, 2014 **Report Images** IMAGE IMAGE AA AB









